EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	3	("4717984" "5644510" "6563685").PN.	US-PGPUB; USPAT	OR	ON	2008/01/21 23:34
L5	2015	700/22,33,79,170,292,293,297,299. ccls.	US-PGPUB; USPAT	OR	ON	2008/01/21 23:34
L6	4142	702/64,88,132,182-184.ccls.	US-PGPUB; USPAT	OR	ON	2008/01/21 23:34
L7	437	361/24,25.ccls.	US-PGPUB; USPAT	OR	ON	2008/01/21 23:35
L8	6460	L4 L5 L6 L7	US-PGPUB; USPAT	OR	ON	2008/01/21 23:35
L9	28	L8 and (((measur\$3 or sens\$3 or measurement or measurement or metrology or detect\$3 or observ\$3 or inspect\$3 or test\$3 or ampmeter or amp-meter or meter\$3) near4 (current or amperes or I)) with ((temperature or temp or thermal\$2 or heat\$3 or cool\$3 or BTU) near4 (load\$3)))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:39
L10	21	L8 and (((measur\$3 or sens\$3 or measurement or measurement or metrology or detect\$3 or observ\$3 or inspect\$3 or test\$3 or ampmeter or amp-meter or meter\$3) near4 (current or amperes or I)) with ((temperature or temp or thermal\$2 or heat\$3 or cool\$3 or BTU) near2 (load\$3)))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:40
L11	29	L8 and (((measur\$3 or sens\$3 or measurement or measurment or metrology or detect\$3 or observ\$3 or inspect\$3 or test\$3 or ampmeter or amp-meter or meter\$3) near4 (current or amperes or I)) with ((temperature or temp or thermal\$2 or heat\$3 or cool\$3 or BTU) near2 (load\$3 or overload\$3)))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:51
L12	22	L11 and motor	US-PGPUB; USPAT	OR	ON	2008/01/21 23:52
L14	3	L11 and ((nominal or regular steady) near4 (current or amperes or I))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:42
L15	1	L12 and L14	US-PGPUB; USPAT	OR	ON	2008/01/21 23:42
L16	4	L11 and ((normaliz\$3 or scal\$4) near4 (current or amperes or I))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:42
L17	4	L12 and L16	US-PGPUB; USPAT	OR	ON	2008/01/21 23:48

EAST Search History

L18	1	L17 and ("32-bit" or "32bit" or "32 bit")	US-PGPUB; USPAT	OR	ON	2008/01/21 23:50
L19	1	L17 and (fixed adj2 point)	US-PGPUB; USPAT	OR	ON	2008/01/21 23:50
L20	1	L17 and ((fixed adj2 point) or fixed-point)	US-PGPUB; USPAT	OR	ON	2008/01/21 23:51
L21	24	(((measur\$3 or sens\$3 or measurement or measurement or measurement or metrology or detect\$3 or observ\$3 or inspect\$3 or test\$3 or ampmeter or amp-meter or meter\$3) near4 (current or amperes or I)) with ((temperature or temp or thermal\$2 or heat\$3 or cool\$3 or BTU) near2 (load\$3 or overload\$3 or over-load\$3))) and ((normaliz\$3 or scal\$4) near4 (current or amperes or I))	US-PGPUB; USPAT	OR	ON	2008/01/21 23:51
L22	1	L21 and ((fixed adj2 point) or fixed-point) and motor	US-PGPUB; USPAT	OR	ON	2008/01/21 23:51
L23	10	L21 and motor	US-PGPUB; USPAT	OR	ON	2008/01/21 23:52